

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

JU1361  
NE  
> 1  
1.719 mi.  
9075 ft.

MANHOLE 57852  
AVENUE U/EAST 14TH ST  
BROOKLYN, NY

NY Spills S106006690  
N/A

Site 2 of 3 in cluster JU

Relative:  
Higher

Actual:  
22 ft.

SPILLS:

Name: MANHOLE 57852  
Address: AVENUE U/EAST 14TH ST  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0205248 / 2003-04-24  
Facility ID: 0205248  
Facility Type: ER  
DER Facility ID: 154038  
Site ID: 184041  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2002-08-19

Investigator: KMFOLEY  
Referred To: Not reported  
Reported to Dept: 2002-08-19  
CID: 405  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2002-08-19  
Spill Record Last Update: 2003-04-25  
Spiller Name: SAME  
Spiller Company: CON EDISON  
Spiller Address: 4 IRVING PLACE  
Spiller Company: 001  
Contact Name: KEVIN MCARDLE  
DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead\_DEC Field was FOLEY Con Ed e2mis #144612: 8-19-02 1015 HRS E. RASA # 42951 OS UG REPORTS WHILE GETTING READY TO SPLICE OPEN MAINS ( SECONDARY ) IN MH57852 S/S AVE U 40' E/O E. 14ST HE FOUND APPROX 1 QUART DIELECTRIC ( OIL ) FLUID NO WATER THAT LEAKED FROM 3C CABLE . THIS IS A D-FAULT # 208-A THAT LOOKS TO BE ON DEAD FDR. K-9 BY DUCTING. THERE IS / WAS NO FIRE OR SMOKE AT THIS LOCATION. NO PRIVATE PROPERTY AFFECTED. NO INJURIES DUE TO THIS OIL. HE DOES NOT SEE A SUMP OR SEWER CONNECTION AT THIS TIME , LIQUID SEEMS CONTAINED. NO SEWERS OR WATERWAYS AFFECTED. HE TOOK A LIQUID SAMPLE AND REQUESTED EMERG PRIORITY FOR PCB SAMPLE RESULTS. CLEANUP PENDING SAMPLE RESULTS AND MAKING D-FAULT SAFE ( TAG OR REPAIR ) . CHAIN OF CUSTODY # CC01893. E.S.TAG # 21489 PLACED. THIS WILL NOT GO ON THE 24 HRS DEMINIMIS PROGRAM DUE TO D-FAULT. METER PARKING. CIG K. MCARDLE NOTIFIED 1116 HRS UPDATE: 10/10/02 - 1100 E. RASA - O.S. - U.G., REPORTS D- FAULT CORRECTED SPOT CLEANUP COMPLETED BY DOUBLE WASHING SPOT WITH SLIX. WASTE REMOVED WITH OIL ABSORB & DIAPERS AND DOUBLE BAGGED. TAG #21489 REMOVED."

Remarks:

"spill from a bad feeder cable - all is contained in the man hole - no waterways affected - coned #144612 - samples taken - will all be

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

cleaned up once the hole is safe to enter"

All Materials:

Site ID: 184041  
Operable Unit ID: 856694  
Operable Unit: 01  
Material ID: 519452  
Material Code: 0541A  
Material Name: dielectric fluid  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 1.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported